



**25 Euro
per hectare**



There has NEVER been a better time
to choose a **new REXOR!**

For over 20 years, we have been setting new standards for harvesting beets, chicory roots and celeriac. We are so convinced of the quality, reliability and performance of our machines that we offer you unique criteria:

- > Up to 4 years warranty
- > 25 € wear costs per hectare
- > A buy-back price defined in advance
based on harvested hectares

See for yourself and contact
your Area Sales Manager.

www.grimme.com

GRIMME

**The 25 € per hectare comprise
the following services:**



1 Maintenance service:

- according to the service booklet (to maintain the factory warranty) with GRIMME Original Parts
- Maintenance of engine parts in accordance with the operator manual by certified technicians
- Maintenance of the hydraulic system
- If necessary, exchange/replacement of the oils and filters according to the operator manual

2 Premium check:

- Journey to the machine location
- Professional inspection of the cleaned machine as part of the Premium Check based on a machine-specific GRIMME checklist
- Documentation of the condition of the machine in the checklist with repair/replacement recommendations
- Offer for the repair of the machine
- The customer decides independently whether repairs are to be carried out by the dealer or by the customer himself

3 Manufacturer's warranty:

GRIMME Landmaschinenfabrik warrants comprehensive coverage of all included repairs within the agreed contract period. This warranty comprises all necessary GRIMME Original Parts as well as arising labour costs and travel expenses. These services are rendered in the agreed region of operation.

4 Wearing parts:

- Wearing parts are replaced independently by the customer's workshop staff
- A GRIMME service engineer provides support during the machine inspection, preparation of the checklist and the initial use
- Wearing parts are those components that are used for economic reasons at points where wear occurs due to operation and that are intended to be replaced

No hidden costs!